

COMMONWEALTH OF PENNSYLVANIA DEPARTMENT OF ENVIRONMENTAL PROTECTION BUREAU OF LAND RECYCLING AND WASTE MANAGEMENT

Inspection Date	10/06/05
Time Start	
Time Finish	

HAZARDOUS WASTE I	NSPECTION REPORT
GENERATOR	◯ S Q GENERATOR

C_{0}	mnany nama Hydromot	ion Inc	LD. Number PAD087343085		
	mpany name <u>Hydromot</u>		I.D. Number FAD907343903		
		ge Street, Spring City, PA 19475	7in 1047E		
		Municipality Spring City			
		a Rose, Waste Management Specialist (mero			
	-	ole Official <u>Jack Jeffers, Support Service Man</u>			
	rson Interviewed <u>Jack J</u>				
	,	nt from above)			
Am	ount of Hazardous Was	ste Generated per Month: <220	_ Pounds Kgs		
1.	Site Characterization	:			
	STORAGE: Cor	ntainer 🗌 Tanks 🔲 Containment Bldg.	Drip Pad Other		
	PBR:				
	GENERATOR TREAT	MENT Containers Tanks	Containment Bldg. Drip Pad		
2.	Universal Waste:	Large Quantity Handler	ntity Handler		
	Universal Waste T	ypes			
3.	Hazardous Waste Tra	Hazardous Waste Transporters:			
	Transporter Name <u>Safety-Kleen</u>		License Number TXR000050930		
		Transporter Name Marisol, Inc. License Number			
4.	·	waste generated and destination facility (lo			
••	. Jpcc ci nazarzone	()	soution a typo).		
	Waste Code	Waste Description	Destination Facility		
	F005, F003, D001, D018, D035, D038, D039, D040	Waste Paint Related Material	Safety-Kleen Systems, Inc. (PAD000738849)		
	F003	Waste Paint Related Material	Marisol, Inc. (NJD002454544)		
	D039	Waste combustible liquid (petroleum naptha)	Safety-Kleen		

COMMONWEALTH OF PENNSYLVANIA DEPARTMENT OF ENVIRONMENTAL PROTECTION BUREAU OF LAND RECYCLING AND WASTE MANAGEMENT

HAZARDOUS WASTE INSPECTION REPORT GENERATORS -- SMALL QUANTITY GENERATORS

Site Name Hydromotion, Inc.	ID Number PAD987343985		Date 10/06/05
1 - No Violation Observed	2 - Not Applicable	3 - Not Determined	4 - Non Compliance

ST	ATUS	8			PA CIT.	FED. CIT.	LINE
1	2	3	4	REQUIREMENT	25 PA Code	40 CFR	NO.
\boxtimes				Hazardous waste determination performed on all waste streams	262a.10	262.11	H001
\boxtimes				Identification Number	262a.10	262.12	H002
\boxtimes				Authorized transporters only	262a.10	262.12(c)	H003
\boxtimes				Subsequent notification requirements met	262a.12(b)		H004
\boxtimes				Proper manifest used	262a.10	262.21	H005
\boxtimes				Manifests filled out correctly and completely	262a.20		H006
\boxtimes				Manifests signed and routed properly	262a.23(a)	262.23	H007
	\boxtimes			Generator waste accumulated on site for 90 days or less	262a.10	262.34(a)	H008
				SQG waste accumulated on site for 180 days max unless 200 mile distance rule applies - 270 days	262a.10	262.34(e)(f)	H009
\boxtimes				SQG waste accumulated on-site never exceeds 6000 kg	262a.10	262.34(e)(f)	H010
\boxtimes				Satellite accumulation requirements complied with	262a.10	262.34(c)	H011
\boxtimes				Personnel training program per 265.16 complied with	262a.10	262.34(a)(4) 262.34(d)	H012
\boxtimes				Manifest exception and biennial reports retained for 3 years	262a.10	262.40(a)(b)	H013
\boxtimes				Specified records retained for three years	262a.10	262.40(c)	H014
	\boxtimes			Biennial reports submitted to the Department (LQG only)	262a.41	262.41	H015
\boxtimes				Exception reporting procedures followed	262a.42	262.42	H016
\boxtimes				Spill reporting procedures followed	262a.10	262.34(d)	H017
\boxtimes				PPC plan developed and implemented	262a.10	262.34(a)	H018
	\boxtimes			Special requirements followed for international shipments	262a.10	262.50 262.60	H019
	\boxtimes			Source reduction strategy prepared and available (LQG only)	262a.100		H020
\boxtimes				Excluded waste complies with exclusionary requirements	261a.4	261.4	H021

ER-WM-129: Rev. 7/95

Commonwealth of Pennsylvania Department of Environmental Protection Bureau of Land Recycling & Waste Management

Inspection Report Comments

Date of Inspection October 6, 2005 Identification Number PAD987343985
Company/Facility/Site Hydromotion, Inc.
A routine inspection of the hazardous and residual waste handling methods at Hydromotion, Inc., located in Spring City Borough, Chester County, was conducted on October 6, 2005 by Melissa Rose, Waste Management Specialist, of the Department. Mr. Jack Jeffers, Support Service Manager, was present for Hydromotion.
A walk around tour of the facility was led by Mr. Jeffers, followed by a paperwork compliance review. Hydromotion, Inc. is a manufacturer of hydraulic swivels, such as those used in big turning crane trucks and twirling amusement rides. Hazardous wastes generated at the facility include lacquer thinner cleaner from the paint booth operation, and mineral spirits from parts-washers.
In the paint booth area is a Model 1111 combination gun and equipment cleaner. Lacquer thinner is used in this cleaner and it is serviced monthly by Safety-Kleen. Hydromotion also utilizes about 5 parts washers which are also serviced by Safety-Kleen. Some of the parts-washers are aqueous and some use mineral spirits. No separate drums of hazardous waste were observed apart from these units.
Non-hazardous water-soluble cutting oil is used in the manufacturing area. This oily water is collected and placed into an oil/water separator. The oil is skimmed of the top and placed into drums, and the water is evaporated. Gemini Disposal Services takes the waste oil/water to Environmental Recovery Corp. in Lancaster. Gemini also takes waste oily rags. Hydromotion should ensure that all drums and containers containing waste oil are properly sealed, in containment, and labeled as "waste oil."
Manifests from Safety-Kleen and Gemini were reviewed and in compliance. Hydromotion should ensure that all its manifests and waste disposal records are kept well organized. Hydromotion's Contingency Emergency Plan (last updated May 2005) is presently in the process of being implemented.
No violations were noted.
This inspection report is notice of the findings of an inspection conducted by a representative of the Department. This report is formal notification of any violations observed during the inspection. Additional notification of violations may be issued concerning either violations noted herein, or other violations identified as a result of review of laboratory analyses or Department records. This report does not constitute an order or other appealable action of the Department. Nothing contained herein shall be deemed to grant or imply immunity from legal action for any violation noted herein.
Signature by the person interviewed does not necessarily imply concurrence with the findings on this report, but does acknowledge that the person was shown the report or that a copy was left with the person.
Person interviewed (signature) Judiffe Date 10/6/05
Inspector (signature) Melisia Kore Date 10/6/05
Page 3 of 3